
CSMIO/IP® Motion Controller Configuration ©CS-Lab s.c. 2010
Axes Configuration
Special Functions
Spindle DAC
Spindle Acceleration/Deceleration
Spindle Encoder (CSMIO-ENC)
Spindle Alarm Input
Close
Apply & Save
Engine Configuration... Ports & Pins
Port Setup and Axis Selection
Motor Outputs
Input Signals
Output Signals
Encoder/MPG's
Spindle Setup
Mill Options
OK
Anuluj
Zastosuj
CSMIO/IP-S
DIGITAL INPUTS (0-15)
PIN number
Details
DIGITAL OUTPUTS (0-15)
Analog inputs/outputs connector
Power Supply Input
Pin number
Description
Power – 24V DC
GND
ground
Power Supply
GND
+24V DC
L
N
PE
Alarm
+24V
FWD/Stop
REV/Stop
GND (0V)
0-10V
Analog GND
SIMENS
SINAMICS V20
DI 1
DI 2
DI C
AI 1
0 V
DO 2 C
DO 2 NC
DO 2 NO